



Project Profile



Project Facts:

- **AREA**
2500 sq. ft. segmental retaining wall
- **OVERVIEW**
Erosion was causing the client to lose a significant amount of land into the lake. The retaining wall was constructed to prevent erosion and allow easier access to the lake.

J. Rockwell Residence Lake Martin, AL

